BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Date : 24-01-2024

No. : 1140

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer, Yelahanka Sub Division, B.B.M.P. Bangalore-64

2. Well Location : Chowdeshwari Layout, Markandeya Temple R/Side, ward-02

3. Total Well Depth / Drilled in Ft. : 983'.00"

4. Casing Erected in Ft. : 200'.00"

5. Water Struck at the Depth of : 300'.00" to 540'.00"

6. Total Yield (Measuring method "V" Norch : 2" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Boulders

8. At the Depth of : 590'.00"

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

AE-2

Party's Signature

A.E.E

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature AE-02

AE-02

Manager / Proprietor

Smt. Ravina Singh

BOREWELL
COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

No. : 1137

Date : 21/01/2024

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer, Yelahanka Sub division, B.E.M.P. Bangalore-64

2. Well Location : Jayaprakash Colony, ward no-02

3. Total Well Depth / Drilled in Ft. : 960.00"

4. Casing Erected in Ft. : 220.00"

5. Water Struck at the Depth of : 550.00" to 600.00"

6. Total Yield (Measuring method "V" Norch : 2" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Boulders

8. At the Depth of : 650.00"

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

AE-2

A.E.E

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature AE-02

Manager / Proprietor

AE-02

Smt. Kavitha Singh

COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Date : 27/01/2021

No. : 1138

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineer, Yelahanka Sub division, B.B.M.P Bangalore-64

2. Well Location : Balaji Layout, 5th Cross, ward no-02

3. Total Well Depth / Drilled in Ft. : 955.00"

4. Casing Erected in Ft. : 180.00"

5. Water Struck at the Depth of : 500.00" to 560.00"

6. Total Yield (Measuring method "V" Norch : 2" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear Boulders

8. At the Depth of : 630.00"

9. Recommended to use Jet Pump / Air Compressor / Submersible /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

AE-2

Party's Signature A.E.E

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature AE-2

Manager / Proprietor

AE-2

Smt. Kavitha Singh

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

Mobile : +91 9342202932 / 9343202932

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore 560094

Date : 29/01/2021

No. : 1139

1. Customer's Name and Address with Telephone No. : Assistant Executive Engineers
Yelahanka Sub division
B.B.M.P. Bangalore-64

2. Well Location : I.SRO Layout 6th Cross, (Near public Toilet Room) ward no-22

3. Total Well Depth / Drilled in Ft. : 990'.00"

4. Casing Erected in Ft. : 200'.00"

5. Water Struck at the Depth of : 480'.00 to 520'.00"

6. Total Yield (Measuring method "V" Norch : 2" / Inches on "V" Norch)

7. Formation of Soil/Well Water Condition : Boulders/Silt/Loose Soil/Clear ✓ Rock

8. At the Depth of : 550'.00"

9. Recommended to use Jet Pump / Air Compressor / Submersible ✓ /Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good/ satisfied / Party agreed conditions.

Once the well handed over to party, company is no way responsible for further developments if anything in the well or what so ever.

A.E.E

Party's Signature

I, owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

Smt. Kavitha Singh